BYE 8712-68
Copy 5 of 11

27 February 1968

Job#69800404R Box#l Folder 72

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6853

1. Mission critique was conducted in the OSA Control Center at 1330 hours, 23 February 1968.

2. Mission Data:

- a. Mission Number: BX6853
- b. Date Flown: 19 February 1968
- c. Area of Operation: North Korea
- d. Mission Success: Successful
- e. Pilot's Name: Murray
- f. Aircraft Number: 127
- g. Primary or Spare Flown: Primary
- h. Takeoff Time Planned: 0205Z

Actual: 0159Z

i. Landing Time - Planned: 0536Z

Actual: 0538Z

j. Time Enroute - Planned: 3+31

Actual: 3+39

- k. Departure Base: Kadena Air Base
- 1. Landing Base: Kadena Air Base
- m. Equipment:
- (1) Primary: TYPE I, BIRDWATCHER, PIN PEG, BLUE DOG II, MAD MOTH, SYSTEM VI.
 - (2) Spare: Same as primary.

GROUP 1
Excluded from automatic
downgrading and
doclassification

HANDLE VIA BYEMAN COMINT CONTROL CHANNELS JOINTLY

OXCART/TRINE

BYE 8712-68 Page 2

3. Operations:

- a. Mission Generation & Operational Support: Satisfactory.
- b. Plans-Route (Actual vs. Planned): Satisfactory.
 - (1) Total INS Nav Time: 4+06 Hours
 - (2) INS Terminal Error: 6.4 Nautical Miles
 - (3) INS Spec Error: 9.0 Nautical Miles
- c. Tactics (Planned vs. Actual): Pilot took off six minutes early due to B-52/KC-135 takeoff time conflict.

4. Weather:

- a. Forecast vs. Actual: as briefed.
- b. Observed Cloud Condition by Pilot: West Coast cloudy.
- c. Comments: Forecast CAT II. 88 percent of programmed targets were cloud free.

5. Materiel:

- a. Aircraft General: Satisfactory.
- b. Aircraft Systems: Satisfactory.
- c. Camera Systems:
- (1) Quality of Take: Satisfactory. Exposure is good. Contrast is good. Exposure appears to be of sufficient spread so that specific targets can be highlighted when reproducing dupe positives from original negative.
- (2) Resolution: Imagery is as good as previous North Korea mission (BX6847) except where degraded by atmospherics.

HANDLE VIA BYEMAN COMINT CONTROL CHANNELS JOINTLY

OXCART/TRINE

OXCART/TRINE

BYE 8712-68 Page 3

(3) Camera Operation: Satisfactory. No malfunction noted.

6. Intelligence:

- a. Target Coverage:
 - (1) 65 of 75 programmed targets covered.
 - (2) 1 SSM target covered
 - (3) 69 of 120 COMIREX targets covered
 - (4) 11 SAM sites, 8 sites occupied, 2 ID only
 - (5) 88 bonus targets
- (6) Comments: The mission obtained good coverage of the southern two-fifths of North Korea. Haze and snow cover hampered interpretation in the mountainous area.

- c. Significant Findings: None.
- d. EWS Activations: None.
- e. Take Movement:
 - (1) Photography: Satisfactory.
 - (2) ELINT: Satisfactory.
- (3) Comments: The pilot's film strip was misplaced in the Headquarter's Signal Center.

7. Communications:

- a. Message Traffic: Satisfactory.
- b. BIRDWATCHER: Satisfactory.
- c. UHF/HF Commo: Satisfactory.

HANDLE VIA BYEMAN COMINT CONTROL CHANNELS JOINTLY

BYE 8712-68 Page 4

8. Significant Actions Taken	8.	Signifi	cant	Actions	Taken:
------------------------------	----	---------	------	---------	--------

a.	DTFC	has	established	procedure	to	preclude	future	B-52/KC	:-135
takeoff	time con	nflic	ts						

b. Film strip delivery and accountability procedure is being reviewed and appropriate action is being taken to preclude recurrence on future take deliveries.

9. Outstanding Actions Required:

a. At alert briefing for next North Korean mission, determine location of U.S.S.R. fleet in Sea of Japan. Adjust EWS and camera turn on to gain maximum intelligence (Intelligence Division, OSA; Office of Scientific Intelligence).

b.	
	OXCART Division;
Intelligen	ce Division; Communications Division; Office of Scientific
Intelligen	ce).

c. Determine reason and insure corrective action for voice distortions noted on SYSTEM VI tape (Materiel, Avionics Division).

Chief, OXCART Division, Operations, OSA

OXC/O/OSA/ Distribution:

#1 - D/SA

#2 - D/O/OSA

#3 - D/M/OSA

#4 - D/R&D/OSA

#5 - OXC/O/OSA

#6 - Intel/O/OSA

#7 - Wea/O/OSA

#8 - Commo/O/OSA

#9 - ADP/O/OSA

#10 - RB/OSA

#11 - Chrono

HANDLE VIA BYEMAN COMINT CONTROL CHANNELS JOINTLY

OXCART/TRINE